






Assembly Instructions



2108







60 min






2108

1	1	1200x400x18MM
2	1	1200x400x18MM
3	2	398x564x18MM
4	1	378x564x18MM
5	2	582x574x5MM
6A	3	578x184x18MM
6B	3	578x184x18MM
7A	6	350x120x15MM
7B	6	350x120x15MM
8	6	531x343x5MM
9	6	521x120x15MM






 φ 15x12 AX12	 M6x35 BX12	 φ 8x40 CX12	 M3. 5x15 DX80
 350mm EX12	 M6x24 FX24	 M6x15 GX12	 M6 HX12
 φ15xM6x1 IX16	 M6x45 JX4	 70x70x20 KX4	 5# LX1
 φ38x190 MX4	 NX6	 OX6	 PX8
 φ 12x12 QX24	 RX24	 SX2	 TX24





1





$E = E1 + E2$





2



3



4



5





CX12



DX36




E2X12



6




AX6




8-14

7



8




9-14

9




Ax6



10




FX24





10-14

11



X6


12



X6


11-14

13



X6



14




X6

12-14

15



16



13-14

17



14-14