







Assembly Instructions



2102






60 min







2102

| | | |
|----|---|---------------|
| 1 | 1 | 1200x400x18MM |
| 2 | 1 | 1200x400x18MM |
| 3 | 2 | 598x164x18MM |
| 4 | 1 | 598x164x18MM |
| 5 | 2 | 572x164x18MM |
| 6 | 2 | 568x160x18MM |
| 7A | 2 | 350x100x15MM |
| 7B | 2 | 350x100x15MM |
| 8 | 2 | 521x100x15MM |
| 9 | 2 | 531x343x5MM |






| | | | |
|--|---|--|--|
|  φ 15x12 AX20 |  M6x35 BX20 |  φ 8x40 CX12 |  M3. 5x15 DX24 |
|  350mm EX4 |  M6x24 FX8 |  M6x15 GX12 |  M6 HX12 |
|  φ15xM6x1 IX16 |  M6x45 JX4 |  70x70x20 KX4 |  5# LX1 |
|  φ38x190 MX4 |  NX2 |  OX2 |  PX8 |
|  φ 12x12 QX8 |  RX8 |  SX2 | |





1





E=E1+E2





2



3





4




7-13

5



6




8-13

7




Ax6



8



BX6





9-13

9




Ax6



10




FX8



X2


10-13

11




X2

12




X2

13



X2



14





X2

12-13

15



16



13-13